

5c, 11, 33.

1E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME *Haw* Rpt. *Hwe.* No. *97822*
Law " *107904*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine *Poil Engines 2 S.C.S.A.*
4 Cy. 23 5/8" - 9 1/16"

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner
If fitted with an outside gland of }
approved type

Yes
No

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *HL MC 8.39*

2 DB
DB (WT) } 120 lb.

"La Mont" WTDB to be considered as Scotch "B" as regards periodical BS's.

L.F.
17/10/39.



© 2019 Lloyd's Register Foundation

W174-0060

W174-0062

ections

on.

Added

ft.

Capacity.

ons.

50

98

46

Ligh

publ

of cr

crank

the

alle to

and ey

er Ra

fitted

er {

r ma

h

sive

he af

prop

uce

M

ter co

to the

essel

work

ing

2/2

ordin

72

aps a

Room

9

in th

water

ng pl

inery

worked from