

50,8,12.

Helka

F.E.

Received by Chief Ship Surveyor 27. 12 12

Received from Chief Ship Surveyor

VESSEL'S NAME *M. S. S. "Mijdrecht"*

Rpt.

*Rot*

No.

*8214<sup>2</sup>*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

*71*

Depth "d"

*21.58*

Framing: Table No.

*5*

Description

*Bulk Angle as approved*

Longitudinal No.

*23075*

Proportions

Length =

*13.54*

Depth =

Deck Sheerstrake

*as per Rule*

5800-111M

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to

be classed  $\frac{1}{100}$  A. 1. *"Trunk Deck,"* Carrying Petroleum in bulk  
as recommended.

$\frac{1}{100}$  A. 1. (SA) *"Trunk Deck"* Carrying Petroleum in bulk  
1 Gr. (SA) & Web frames

P.K. p<sup>t</sup> Asp. 15 BH Ledges a r b t P 71. F 33



© 2019

Lloyd's Register  
Foundation