

or Previous Registry (if any).

Whether a Sailing Steam, or Motor Ship.

Where Built

When Built

Name and Address of Builder

1E

Engineer Surveyor

Received from Chief Engineer Surveyor

*Comus.*

*Rel.*

No. *10750*

The Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also pointing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points stated in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Engine

*oil engines 4 S.C.S.A.*

Boilers fitted with forced draught

Shaft. If fitted with a continuous liner

If fitted with an outside gland of

approved type

*Yel.*  
*no*

The vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is to be classed *+HMC 12-71*

*2019.150A*

*[Signature]* *31/10/31*



© 2020

Lloyd's Register Foundation

*W18-0054*

Certificate of Competency No.