

1E

Revs. 7

f Cran

kness pa

kness are

inuous 1

of the 1

he liner

ad non-c

fitted a

porting

doped S

the other

the other

Main E

-2

ctions

pines to

below th

and bras

rgo or m

worked

g Pres

Don

ents

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SEL'S NAME

Iron Chieftain

Rpt.

Grk. No. 20479
Grk. No. 5-9185-
Grk. " 104037
104036

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Quadruple Expansion & Exhaust-
Turbine driving Steam compressor.

NHP for R.B. 5-5-3.

If Boilers fitted with forced draught

Yes

Tail Shaft. If fitted with a continuous liner

Yes

If fitted with an outside gland of

No

approved type

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ LMC 10.37

Sph.

24
3/11/38.



© 2021

Lloyd's Register
Foundation

W181-0037