

Vessel's Name S.S. "J. N. PEW"

Dry Dock

3m. 4.21.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stat S.S. "J. N. PEW"

Report Pl No. 4213

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____ When due _____

✱ 100-A-1. (Steel) "Shelter Dk with freeboard" "Carping petroleum in bulk"
 1 Dk. (Steel) & Shelter Dk (Steel) & Webframes, "Longitudinal framing"
 Cell II B & E & B 89' f 40' 1448t, FPT 186t, APT 84t.
 FK, 18 BH (10 to Shelter Dk, 8 to upper Dk) pt Cen, Av CP, F 44' on Shelter Dk
 Achy aft

M *H*



© 2013 308-21

Lloyd's Register Foundation

W181-0093

Particulars for record in Register Book.

Freeboard 10 ft. 6 ins.