

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl Tw. Sc. "JAGERSFONTEIN" Rpt. Ans. No. 13349a

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

1st Long. No. 17658.3 Depth "d" -

2nd Long. No. 46426.6 Proportions = $\frac{L}{D}$ 11.81

Framing Bulb angle and channel etc. Sheerstrake as approved
as approved

1097 fms

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

 100A1

3 Dks

Cell DBuE & f 239' 675t, Tanks in way of Tunnels 1127t, FPT 159t, APT 124t

FK, 8 BH, pt Cem, Lloyd's A & CP

P 32', B 175', F 35'

Handwritten signatures and date: 7.1.35



© 2019

Lloyd's Register Foundation

W182-0008