

1

Fee Paid

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME

"KOOLAMA"

Report

Gls.

No.

59572

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*First Entry*

When due \_\_\_\_\_

100A1 "With Freeboard"

1 Dk., 2nd dk. in forward holds.

Cell.DB 277' 812t, tanks between tunnels 114t, FPT 37t, APT 87t.

FK, 6BH., pt.cem., Lloyd's A & CP.

Shade dk., F. on Shade dk. 41'.

O.L.362.25'.



© 2021

Lloyd's Register  
Foundation

*WRS-0168*

INCORPORATED  
✓  
✓  
✓  
57  
3"  
4"  
NE.  
42"  
3"  
1/2"  
T.  
ERT  
6"  
EYE  
VED  
7"  
9"  
10"  
LAS  
OVE  
1/2"

.....)  
.....) EVERY