

Hanover

Nov. 100 385

Before his case receives consideration
submitted the Hwc Surveyors be
requested to state whether any action
has been taken regarding the alignment of
the main hygienic sewers referred to
in N.Y. report 42203 which was sent to Hwc
on May 4th for the Surveyors information.

W. J. 8/6/42

W189-0145

OIL ENGINE SURVEYS.

F. E. BROVIC

SURVEY DUE

DATES OF SURVEY.MAIN ENGINE.

Numbered from forward.

tons, valves, gears

s & top ends.

rnals.

No.1	No.2	No.3	No.4	No.5	No.6	No.7	No.
733	733	1.33	733	733	1.33	733	733
"	"	1.33	"	"	1.33	"	"
"	"	1.33	"	"	1.33	"	"
"	"	"	1.33	"	"	"	1.33

© 2020

Lloyd's Register
Foundation