

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Stl S MARGOT Report Enk No. 18626**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey 1st Entry When due Revised Rules

✠ 100 A.I. (Steel).

2 DKS (Stl)

Cell D.B 329' 1003t, D.T.a 30' 760t, A.P.T. 16t.

F.K., "Intermediate between SK B.H in after hold dispensed with

4 B.H to upper SK, 2 B.H. to 2nd DK.

pt Cen, Lloyds A & C.P. P33' B 112' F 44'.



© 2019

Lloyd's Register
Foundation

W194-0152

8.12.26.