

REPORT OF SURVEY FOR REPAIRS,

Copy.

Rpt. 12.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

When received in London Office

Port Amsterdam

Vessel's Name S.S. "Besario" ex "D.A. D.G. 76"

Official No. 144 663 No. in Reg. Book _____

Port of Registry (For Foreign Vessels) _____

Iron or Steel Steel State whether Classed by Lloyd's Register Contemp.

Name of Owners _____ Date of Verification 22. 7. 21

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	5 ft.	1/2 ins.
From centre of disc to top of statutory deck line } at awning or part-awning deck . . . }	✓ ft.	✓ ins.
Fresh Water line above centre of disc . . .		6 ins.
Indian Summer line above centre of disc . . .		6 ins.
Winter line below centre of disc		6 ins.
Winter North Atlantic line below centre of disc		✓ ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side	at main, spar or upper dk.	1 3/4 ins.
<i>steel</i> wood or iron deck with the vessel's side	at awning or pt.-awning dk.	✓ ins.

condition of class.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

(Sgd.) H. N. Bernoski Surveyor.

(To be filled up in London Office.)

Statement No. _____ Date of Committee's Minute 8- 7-21

Particulars for record in Register Book.	Moulded Depth	29 ft.	7 ins.
	Freeboard	5 ft.	1 1/2 ins.
	Corresponding Draught	24 ft.	9 ins.

Freeboards compared and found correct by _____ Date _____

Fee paid? _____ Form for Certificate _____

Instructions _____ Date _____

Certificate written _____ Noted for posting _____



© 2019

Lloyd's Register Foundation

W195-0036