

Engine Room ...
Gross Tonnage
Less Crew Space
Less above Crown of

191.99
31.60

Depth "d," at middle of length (See Secs. 2 & 13) 11.41

Owners ...
Managers
(Where necessary to be entered in Reg. Book.)

1

how named Murra

Sent to Chief Surveyors Jul 29. 14

Received from Chief Surveyors

VESSEL'S NAME Steel Sc Lug "Wrestler" Report G/s No. 34231

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry.

When due

100 A.I. (Steel) "For towing purposes."

1 DK (Steel)

B.K. 7" 4 B.H. Cem. Lloyd's A.C.P.

E. G. G. W. W. W. A. P.
29.7.14



© 2020

Lloyd's Register
Foundation

W198-0167

" Angles on upper edge

" Tie Plates
" Deck. Material and thickness