

GENERAL REMARKS—(continued).

PARTICULARS FOR RECORD in the REGISTER BOOK.—Length of Poop ft., R.Q.D. ft., Bridge ft., Forecastle *on Shelter 40*
(in feet and tenths). When the Poop is joined to the B.D., this should be distinctly stated

No. and Material of Decks (if Iron or Steel) and whether wholly or partially covered with wood, and No. of tiers of Beams (this information is to be given as should appear in the Register Book) *1 Dk (Stl) and Shelter Dk (Stl) 612hds to Shelter Dk 2 to Upper Dk.*

Official No. *140632*; Signal Letters

State if Machinery is fitted aft *no*

How are the surfaces preserved from oxidation? Inside *Paint Portland Cement & Bitumastic* Outside *Paint*

PARTICULARS OF WATER BALLAST.—State whether the Double bottom is constructed on the cellular system or with girders on floors. *Cellular.*

Where Fitted.	^a Length. Feet.	Water Capacity. Tons.	Where Fitted.	^a Length. Feet.	Water Capacity. Tons.
Double bottom, aft,	<i>120</i>	<i>511</i>	Fore peak tank,		<i>91</i>
Double bottom, under Engines and Boilers,	<i>41</i>	<i>213</i>	After peak tank,		<i>120</i>
Double bottom, if under Engines only,			Deep tank, aft,		<i>858</i>
Double bottom, if under Boilers only,			Deep tank, forward,		
Double bottom, forward,	<i>182</i>	<i>847</i>	Other tanks, if fitted,		
Total capacity of double bottom		<i>1571</i>	(If necessary, furnish further information by sketch.)		

* The wells are not to be included in the lengths of the tanks.

State whether the above have been tested as required by the Rules *yes*

Order for Special Survey No. *635*

Date *16-2-18*

No. *555* in builder's yard.

DATES of Surveys held while building

From 23rd Sept: 1918 to 26th June 1919

Total No. of Visits *34*

Surveyor's Signature

S. Kendall

© 2019

Lloyd's Register Foundation