

# Condition of Class.

NAME OF VESSEL..ORCADES.....

Extract from Freeboard verification of marking form received  
from the....BARROW.....Surveyors dated the...2.7.37.....

Moulded depth	38 ft.	0	ins.
Corresponding draught	30 ft.	2	ins.
Moulded depth as shewn on draught sheet	38 ft.	$0\frac{1}{2}$	ins.
Tropical freeboard	7 ft.	$7\frac{3}{4}$	ins.
Summer "	8 ft.	$3\frac{1}{4}$	ins.
Winter "	8 ft.	$10\frac{3}{4}$	ins.
W.N.A. "	- ft.	-	ins.
Fresh Water allowance	$7\frac{1}{2}$	ins.	

$2\frac{1}{4}$ " composition on  
Marked from ~~wood~~/steel upper deck.

Checked by...Mm...

Date...22 JUL 1937.....



© 2020

Lloyd's Register  
Foundation

W204-0077