

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME STE T.S.S. TIEN KWANGReport SlNo. 44463**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey _____

1st Entry

When due _____

† A - (Steel) "Carrying petroleum in bulk"
 "For service on the Yangtze River"

1 SK (Stl) o-weld frames

Cell D.B

F.P.T. 10t.

F.K., Q.B.H., Shade dk 134' F 22'.

The Surveyors should be asked to state the capacities of the tanks corresponding with the length of 64 feet.

6710-222M

