

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Shells Tyleboat

Rpt.

Rpt.

No. 10622

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

84

Depth "d"

18.58

Framing: Table No. 3 page

Description

Bulk angle as approved

Longitudinal No.

35280

Proportions

Length

Depth

11.12

Bridge

Deck Sheerstrake

as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A 1 (Steel) as recommended.

2 (Steel & Teak) 3<sup>rd</sup> class of Beams in her 1<sup>st</sup> Hold S.

cell 5B 353 11056. D.T. a 23 9146. F.P.T. 826. C.P.T. 136

FK. 8BH. Cam. at CP. P 58 B 252 F 65

Date of Build 2.18.

18.11.18



© 2019

Lloyd's Register  
Foundation

W223-0172