

of Framing Girder.....

180

Vertical Angle to Tank side
Bracket abaft $\frac{1}{4}$ len. from

SINGLE ANGLE

224.

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

2 - DEC 1925

VESSEL'S NAME

Stl Se "VALENCIA"

Rpt.

1479

No. 50

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ture of Survey

Damage.

20 await 1st Entry report

8
1-12-25



© 2020

Lloyd's Register
Foundation

W226-0062