

For the information of Surveyors and the Committee only.

Received at

Office

19

Lloyd's Register of Shipping.

(Report on Vessel No. _____ Port _____)

66

SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by AB. Lindholmen Motala Motala Verkstad for the Vessel No. 24, being built by Sjö Tross AB. Orsund of Lundskrona, been inspected by me as set forth below and found to be, so far as can be seen, sound and free from defect.

or Castings.

8
8485
B.

Gothenburg, 9th September, 1920,
W. Aulow

	STERN FRAME.	RUDDER FRAME.	STEM.
Material	S. A. Steel.	/	
Condition	Forged.		
Dimensions	230x140 mm / 205x140 mm.		
Inspection	Finished.		
Inspected	9.9.20.		
Strength Test			
Yield Point	23.0 & 20.4		
Tensile	38.6 & 39.0 %		
Structure	✓		
End ...	✓		
Complies with Rules / Factory	✓		

PLANES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

(Chargeable) £ ✓ :
paid at Gothenburg.



© 2019

Lloyd's Register

Foundation

state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

W226-0070