


Centre Mark

undersurface of piece
of outer built strap
sketch A.

Full size



W226-0179 Outer strap

almost disappeared, a black mark about the size of a pin head
out half the depth of the hole being all that could be seen.



© 2000
Lloyd's Register
Foundation

5126 10

127