

FEET.

Framing Depth "d," at middle of length. See Sec. 3 (1d) Proportions—Depth to Length, Timbers, etc.

20.12

Residence R. Miller

26.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Std & VEERHAVEN Rpt. Std No. 30295

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1<sup>st</sup> Entry

This vessel has left Sunderland for West Hartlepool to have the machinery installed.

It is submitted the West Hartlepool Surveyors be advised and requested to give the case the necessary attention and forward a report on form 8 when the survey has been completed. To complete survey re report.

Str. 24/2/30



© 2020 Lloyd's Register Foundation W226-0214

Handwritten initials and date: 24.2.30

WARD. State Particulars

Single frames ✓  
double riveted ✓  
& thickness shell ✓

BEAMS.

Innermost Continuous Deck

Half