

Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Braganza

Report

hyk

No.

*39953***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

S.S.

No.

SURVEY PARTLY HELD.

due

5.41

When proposed to be completed

not stated

of Survey held, &c.,

See form 48.

*Subject to main engine bedplate be specially examined
on vessels return to hyk from present voyage to Far East*

It is submitted that
his vessel is eligible for fresh
RECORD of Survey

2.40. for the oil engines.

*Noted**Thun**4.11.40*

© 2019



Lloyd's Register
Foundation

*The American manifest of +Lund 240
is not in order & the High Surveyor should be advised
It is possible they intended W 234-0010 under date*

W 234-0010

W 234-0010