

Lloyd's Register of Shipping.

Port of HULL.

19th May, 19 44.

Dear Sir,

We beg to return herewith report of survey as indicated on the reverse side, recently forwarded to us for guidance in the survey of the vessel.

We are, Dear Sir,

Yours faithfully,


The Surveyors,

Per: -

John W. Browne.

The Secretary,

~~London~~ **Wokingham.**



© 2020

Lloyd's Register
Foundation

At request of owners representative examined for break down

Vessel.	Port of Survey, and No. of Report.	Particulars of action taken in the case.
"DUNGRANGE"	Bry.25112, 25058, 24963, 24869, 25864, Cff.54258, 52149, Bry.24639, 24631,24557.	Please see our report No. 52438 on the case, forwarded today.



© 2020

Lloyd's Register
Foundation

W240-0044

2m.11.42. (MADE AND PRINTED IN ENGLAND.)

REVERSE FRAMES

Longitudinals

SHIPMENT

Have Sluice Valves been examined and found

Caulking

Treenails

Anchors, L

Cables (S