

1

E. G. Seabert

Sent to Chief Surveyors 1. 1. 19.

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "E.L. DOHENY THIRD". Report Phl. No. 3042

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

✱ 100 A.1. (Steel) Shelter Dk. with freeboard.

Carrying petroleum in bulk.

2 Dks. (Steel) and Shelter Dk. (Steel) and Webframes.

Longitudinal framing.

Cell DBa 23' u E. & B. 76. 463t. DTf40' 44lt.

FK. 17 BH. (Collision BH. to Shelter Dk. 10 BH. to

upper dk. 6 BH. to 2nd. Dk.)

pt. Cem. A. & C.P. Machinery aft.



2. 1. 19. 2020

Lloyd's Register
Foundation

W240-0218