

Rpt. 7a.

For the information of Surveyors and the Committee only.

S.S. LEOPOLDVILLE

Received at _____ Office, _____ 19

2249/36.

SUPERHEATER
SAFETY VALVES.

Lloyd's Register of Shipping.

(Report on Machinery, No. 20886 Port *Arak*)No. *V* 2517.

ENGINE or BOILER VALVES or CONNECTIONS.

I have to report that the Details, as herein described, manufactured by *John A Grant* of *Cardonald* for the ~~Engines or Boilers~~ ^{Repair} No. 249/36 being constructed by *The North Eastern Marine Eng Co Ltd* of *Wallsend on Tyne*, have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects.

These have been despatched to *Wallsend*

Stamp Mark.

LLOYD'S TEST.

432 lbs.

No.

FRD. 15/9/36.

FR Dale

Glasgow

Number and Description.	4-2" dia C.S. single spring Superheater safety Valves.
Hydraulic Test: lbs. per square inch.	432 lbs/sq. in.
Other Tests, if any.	
Dates when Inspected.	15/9/36.

