

For the information of Surveyors and the Committee only.

Received at

Office

19

Lloyd's Register of Shipping.

457 L.

(Report on Vessel No. 20753

Port

Rot

4. SHIP ~~FORGINGS~~ OR CASTINGS.

have to report that the undermentioned ~~Iron~~ ~~Steel~~ ~~Forgings~~
~~Ruhrstahl A.G.~~
 , manufactured by Messrs. Stahlwerk Krieger
 eldorf for the Vessel No. 618 , being built
 rs. Van der Giessen & Zoonen's of Krimpen
 n inspected by me as set forth below and found to be, so far as can
 l propeller bracket sound and free from surface defects.-

Castings.

Düsseldorf 30th August 1930.

50.

1 propeller bracket

	STEAM FRAME	RUDDER FRAME.	STEM.
...	Annealed Siem. Mart. Cast Steel		
...	cast		
...	Yes		
...			
ion ...	rough turned		
...	29.8.30.		
Test	.798 3"		
...	31,9 31,7		
...	29,5 28,0		
...	120 degr. good		
...	7 feet		
Rules ry ...	satisfactory.		

ES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

chargeable) £ : :

id at Düsseldorf.

e whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

W252-0016

external surfaces of the receivers be examined and cleaned

Is a drain fitted at the lowest part of