

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report.....19..... When handed in at Local Office.....19..... Port of Sydney N.S.W.
 No. in Survey held at Sydney N.S.W. Date, First Survey 12/3/42 Last Survey 31/3/42 19
 eg. Book. 18428 on the Steel T.S.M.S. "Matafele" (No. of Visits 4)
 TONNAGE: 335 Built at Hong Kong By whom Hong Kong Whampoa Dock Co. Ltd. YEAR. 1938 MONTH. 11
 GROSS 335 Owners Burns Philp & Co. Ltd. Owners' Address ✓
 UNDER DK. 206 Managers ✓ (If not already recorded in Appendix to Register Book).
 NET 186 Port belonging to Hong Kong

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Sydney Harbour Destined Voyage.....
 LDBorDBa.....feet; uE & B.....feet; f.....feet
 al capacity.....tons. FPT.....tons; APT.....tons; MT.....feet.....tons.

N.B.—All alterations in the existing records should be underlined.

ast Report, No. 8548 Port L.A.

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.....
 Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

MARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fairred or Repaired								
Fairred or Repaired in place								

ENT CONDITION OF THE

ing of Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
ngs	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
s & Fastenings	Cement or Asphalt	Oil Bunkers	Boats
e Plating	Rudder	Scuppers	Masts, Yards, &c.
in way of sidelights	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
s	Windlass	Hatches	Equipment letter
se Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
udinals	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
verses	Have Watertight Doors been examined and found efficient?	Treenails	length (on board.) mean diamr.
ns	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Rule length size
rs	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Bottom Plating	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
the Tanks been examined internally?		" " at other places	Standing and Running Rigging
the Tanks been tested?		Stringers, Clamps & Shelves	Sails
		Salting (State if examined.)	

neral Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Fee (per Section 29)	£	:	:	Fees applied for,
Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
ling Expenses (if chargeable)	£	:	:	Received by me,
Surveyor's Fee (if any)	£	:	:	19


mittee's Minute

TUE 8 DEC 1942

Character Assigned

As now Subject
 P. S. No. 1-42
 + dmb. 3. 42

Surveyor to Lloyd's Register of Shipping.



© 2019

Lloyd's Register Foundation

W252-0042