

# INSPECTION CERTIFICATE FOR FURNACES.

## WILLIAM BEARDMORE & COY., LTD.

EMS.

PARKHEAD FORGE ROLLING MILLS  
— AND STEEL WORKS —

Glasgow, E. 1st November 19 24


To Messrs. Vickers Limited

Engine Department,      Barrow-in-Furness.

| Date of Order | Order No. | Boiler No. | Test Nos. | DESCRIPTION.                  | DIMENSIONS.    |                |                   |
|---------------|-----------|------------|-----------|-------------------------------|----------------|----------------|-------------------|
|               |           |            |           |                               | Internal Diam. | Lgth. over all | Thickness         |
| 11/7/24       | 16692/E   |            | 57 ✓      | Nineteen S.M. Mild Steel      | 3'4½"          | 8'8½"          | $\frac{11}{16}$ " |
|               |           |            | 166 ✓     |                               |                |                |                   |
|               |           |            | 166.A. ✓  | lapwelded corrugated marine   |                |                |                   |
|               |           |            | 167 ✓     |                               |                |                |                   |
|               |           |            | 167.A. ✓  | boiler furnaces (Deighton     |                |                |                   |
|               |           |            | 168 ✓     |                               |                |                |                   |
|               |           |            | 168.A. ✓  | section) flanged with Stephen |                |                |                   |
|               |           |            | 169 ✓     |                               |                |                |                   |
|               |           |            | 169.A. ✓  | Gourlay withdrawable back     |                |                |                   |
|               |           |            | 169.B. ✓  | ends, and finished all in     |                |                |                   |
|               |           |            | 170 ✓     |                               |                |                |                   |
|               |           |            | 171 ✓     | accordance with sketch for    |                |                |                   |
|               |           |            | 171.A. ✓  | the boilers of ship No.617.   |                |                |                   |
|               |           |            | 172 ✓     |                               |                |                |                   |
|               |           |            | 172.A. ✓  |                               |                |                |                   |
|               |           |            | 173 ✓     |                               |                |                |                   |
|               |           |            | 173.A. ✓  |                               |                |                |                   |
|               |           |            | 192 ✓     |                               |                |                |                   |
|               |           |            | 192.A. ✓  |                               |                |                |                   |

Tested and Inspected by LLOYDS

Representatives at our Parkhead Works, and Material and Workmanship found satisfactory.

*[Signature]*  


LLOYDS



Signed Certificate for

the Mechanical Tests of the Plates attached herewith.

W253-00 69

© 2020

Lloyd's Register  
Foundation