

Rpt. 6.

For the information of Surveyors and the Committee only.

Received at _____ Office, _____ 19

Lloyd's Register of Shipping.

(Report on Vessel No. 41131 Port GLASGOW.)

SS Maria Pyriakides

No. 5764 SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Iron or~~ Steel Forgings or Castings, manufactured by Messrs W Broadfoot & Sons of Glasgow for the Vessel No. 389, being built by Messrs Bow MacLellan & Co of Paisley have been inspected by me as set forth below and found to be, so far as can be seen, Sound

Mark on Forgings or Castings.

Lloyd's

No. 5764

J.D.

Rudder crosshead

Glasgow

	STERN FRAME.	RUDDER FRAME.	STEM.
Material* ...	<div>/</div>	SM Engd Steel	<div>/</div>
How made ...		Forged	
Dimensions ...			
Progress on Inspection ...		Forging & testing	
Date when Inspected ...		11.6.20	
CASTINGS.			
Tests on Standard Test Pieces.			
<u>Tensile Test—</u>		32.0	
Tons per square inch ...		34%	
Extension per cent. ...		180	
<u>Cold Bending Test—</u>			
Angle before fracture ...			
<u>Drop Test—</u>			
Height from ground ...			
<u>Hammering Test—</u>			
If made according to Rules and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ nil

To be paid at

* If of Iron, state whether scrap or puddled Iron. If of steel, state whether made on the Open Hearth process.

2m.2.16. T.



© 2020

Lloyd's Register

U253-0107

Plates. (DECK)

Bow McLachlan & Co.
Forging Report
No. 389.

Maria Kyriakides.



© 2020

Lloyd's Register
Foundation