

ed by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

EL'S NAME "PUNTA GORDA"..... REPORT Aru. No. 552

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The ARUBA Surveyor reports (8.44) this vessel placed on slipway, bottom coated, 30 fathoms of chain cable renewed and verified with certificate, 2 deck plates renewed and minor repairs effected.

Due to damage by collision, repairs have been effected to several shell plates, frames, and beams etc.

It is submitted the vessel is worthy to remain as classed with record of docking survey 8.44.

8.44 Aru.

CSM  
JH  
25/10/44



© 2019

Lloyd's Register  
Foundation

W257-0165