

F.E.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Stl T.S. "PUNTA GORDA" Rpt. Bel No. 9972

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.

Reverse No. 4575Depth "d" 13-25Fig: Table No. 1Description Bull angle frames as approvedLongitudinal No. 19825

Proportions

Length

20-33 5 U.D.

Depth =

13-45 5 Trunk D"

Deck Sheerstrake

as approved

Revised Rule

This vessel appears to have been built in accordance with the
and the approved plans, and it is submitted she is eligible to
be classed

✠ 100A.1. (Steel). Carrying Petroleum in Bulk.
10" (Stl)

Wing tanks + 286t, wing tanks a 356t, F.P.T. 60t, A.P.T. 75t.
F.K, 7 B.H, pt cen, Lloyds A CP.
P 67', TRUNK 204', F 34'. Machinery aft.



© 2019
Lloyd's Register
Foundation

W 251-0175