

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "SVAVA" REPORT *Inc.* No. 101902

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

The 3rd S.S. No.3 due 4.42.

A notation of "Examined 4.42" - 12 months had been assigned.

A further GENERAL EXAMINATION has been held with the exception of the examination of the bunkers.

The class is subject to indented shell plating, framing (p & s) and (fractured) No.2 shell plate from stem in 3rd strake below sheer (s.s.) etc., to buckled stem and stem plating, indented tunnel plating etc. being permanently repaired and starboard hawsepipes being renewed at the first convenient opportunity and to (30 fathoms of chain cable being supplied).

Set in forecastle sheerstrake plate etc. (p.s.f) requires to be dealt with at the Owners' convenience.

Action has been deferred for completion of General Examination.

The NEWCASTLE Surveyors report this vessel afloat and the GENERAL EXAMINATION as above, now completed.

IT IS SUBMITTED the vessel is worthy to remain as classed subject as above ^{and outstanding requirements} and to have notation of "Examined 7.43" valid for 12 months assigned as recommended.

AS now, subject.

"Examined 7.43" - 12 months.

J.F.
7.3.44



© 2019

Lloyd's Register
Foundation

W263-0002