

F.E.

Chief Ship Surveyor 29.7.16

Received from Chief Ship Surveyor

NAME

Sheels Uskmonth

Rpt.

SLS

No. 26767

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

61.0

Depth "d"

16.25

Table No.

3 page 10

Description

Bulb angle

Longitudinal No.

17669

Proportions

Length

= 10.5

Depth

Deck Sheerstrake as per Rule.

The vessel was examined in dry dock & the
bottom cleaned & coated on the 25th July.

This vessel appears to have been built in accordance with the
plans and the approved plans, and it is submitted she is eligible to
be classed ✱ 100A-1. (Steel) as recommended.

✱ 100A-1. (Steel)

1 DK (Steel) well deck

DB $\frac{1}{2}$ 385 E DTA 90 624 E. F.P.T. 94 E.

FK. SBH. Cam. Lacer. Pri Q 90. B 59' F 29'

Date of Build. 5-16

The Surveyor should be requested in future cases
to insert on the 1st page the dimensions of floor in S.B.
Space & also the particulars of the above survey
at Canton.

Lloyd's Register
Foundation

W263-0132