

Received by Chief Engineer Surveyor .....

Received from Chief Engineer Surveyor .....

VESSEL'S NAME Sutlej Rpt. GL No. 62180.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(\*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Oil Engines 2 S.C.S.A.  
3 Cy. 20 1/2" - 8 1/8"

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of approved type

Yes  
No

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ LMC 3.40  
2 DB 120 lb.

L.G.  
8/4/40.

It is concluded that the diameter of the screw shaft should read as 13 1/4" as in the case of the sister vessel, instead of 12 1/2" as stated; but this should be confirmed.

Yes



© 2019

Lloyd's Register Foundation

W263-0159