

# Condition of Class

## Tonnage Opening Fitted

NAME OF VESSEL... VIVA .....

Extract from Freeboard verification of marling form received  
from the.....OSLO.....Surveyors dated the 30.4.38.....

Moulded depth 23 ft. 6 ins.

Corresponding draught 22 ft. 3 ins.

Moulded depth as shown  
on draught sheet. 23 ft. 6 ins.

Tropical freeboard 0 ft. 11 $\frac{1}{4}$  ins.

Summer " 1 ft. 4 $\frac{3}{4}$  ins.

Winter " 1 ft. 10 $\frac{1}{4}$  ins.

G.P.A. " - ft. - ins.

Fresh Water allowance 6 ins.

Marked from xxxx/steel upper deck.

Checked by.....*MW*.....  
Date **27 MAY 1938** .....



© 2019

Lloyd's Register  
Foundation

W267-0019