

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Princess Victoria

Rpt.

Wintour

No.

*61311**61144**172**107273**20840*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

*Oil Engines 2 S.C.S.A.**14 Cy. 18 $\frac{7}{8}$ " - 27 $\frac{9}{16}$ "*~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner

No

If fitted with an outside gland of }
approved type

Yes

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *F L Mc 6.39*

It is concluded the scanning of the air receiver for the whistle are in accordance with the approved plan, but this should be confirmed as the particulars have been omitted from the report.

Yes

© 2021

17/11/38

Lloyd's Register
Foundation

W285-0117