

3m, 0.37.

The 3rd S.S. No. 2 due 1.44

Subject to indented plates D 5 & 6 etc (p.s.) being dealt
with at Owners' convenience.

19 NOV 1944

11

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME "SEINE" Rpt. Sws No. 23531

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey _____

The SWANSEA Surveyors report this vessel placed in
dry dock, bottom cleaned and coated, ~~repairs to~~
and minor repairs effected.

It is submitted the vessel appears worthy to remain as
classed with record of ^{docking date} ~~survey~~ 10.44 as recommended, subject as above.

10.44 Sws, subject.



X The Surveyor has omitted reference to the Conditions of Class
in his recommendations.

astings	-	Rudder	Good.	Scanners	Good.	Boats
---------	---	--------	-------	----------	-------	-------