

For the information of Surveyors and the Committee only.

Received at _____ Office, _____ 19

Lloyd's Register of Shipping.

(Report on Machinery, No. _____ Port _____)

No. 8691.

FOR CLARKSON EXHAUST GAS AND OIL FIRED BOILER
ENGINE ~~or~~ BOILER VALVES ~~or~~ CONNECTIONS.I have to report that the Details, as herein described, manufactured
by Messrs. Chas. Mc. Leil Ltd, of Glasgow.ORDER
for the Engines ~~or~~ Boilers No. EW/83240 being constructed by
Messrs. Harland & Wolff Ltd, of Belfast.
JOB No. 15189.have been inspected by me as set forth below, and found to be, so far as can
be seen, sound and free from defects.

These have been despatched to Messrs. Harland & Wolff Ltd, Belfast.

Stamp Mark.

LLOYD'S TEST.

lbs.

No. 8691.

W. A. Smuss.


Glasgow. 19/5/1939.

Number and
Description.1. The Leil type Manhole Door 16x12x 7/16".
TEST No. 9046.Hydraulic Test:
lbs. per square inch.

Other Tests, if any.

Dates when Inspected.

18/5/1939. See. NIL.



© 2019

Lloyd's Register
Foundation

W292-0136