

Port of London

27<sup>th</sup> September 1921

REPORT ON MASTS, SPARS, AND RIGGING.

Having, in accordance with your instructions, examined  
the Masts, Spars, and Rigging, and Iron Work of same, of the  
S/S Burford Bridge

I have to report that I found the masts, forestay,  
main shrouds, mizzen shrouds, mizzen mainstays  
and iron work all in good condition.

W<sup>m</sup> Robinson

London Shipwright.

L-10-0

Surveyors,  
Lloyd's Register of Shipping,



© 2019

Lloyd's Register  
Foundation

W295-0211