

2m.11.28.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *St S ANGLESEA ROSE* Report *Gls* No. *50553*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey *1st Entry* When due Revised Rules

✠ 100 A.I. (Steel)

1 D^k (Stl) Well D^k

Cell D.B. 144' 231t, F.P.T. 845, A.P.T. 415.

F.K, 4 B.H, pt Cem, *Clayds ACP.*

Q 123', B 12', F 24'

machy aft.

The Certificate of Classification to be endorsed "*Cargo battens not fitted*" and the same notation to be printed in the Register Book.



© 2020

Lloyd's Register Foundation

W3 - 0081

thickness of Intercoastal Plate...

Angle

Spacing

Quarta

Reon Deck Angle 5 or 5