

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Steel S.S. "HERON"*Report *Als.*No. *39852*

## For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

When due

✱ 100 A.1. (steel) "Shelter Dk with freeboard"

1 Dk (steel) & Shelter Dk (steel - w.s) of 2<sup>nd</sup> Dk. (steel in No 1 Hold)

Cell DB 213' 338t.

FPT 17 t.

APT 19 t.

FK. ↓ ~~5 BH.~~ Cent. Lloyd's A.G.P. 863' on Shelter Dk.

Collision BH to Shelter Dk. 4 BH to upper Dk.



© 2020  
30-4-20  
Lloyd's Register  
Foundation

W300-0027