

2 E

Chief Engineer Surveyor .....

Received from Chief Engineer Surveyor 15 JUN 1946

NAME "MONTE ISABELA" Rpt. Bbo. No. 9929

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

Survey ~~COMPLETION OF~~ SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 3


This Survey, due 1.46 now partly held new

completed, and the following repairs carried out (due to wear & tear):-

Screwshaft examined, a number of condenser tubes renewed and a few stays and tubes in the boilers renewed.

It is submitted the vessel is eligible to remain as classed, with notation of LMC 3.46, S 3.46 as recommended.

4.6.46



© 2020

Lloyd's Register Foundation

5510 - 0155  
W304 - 0155

Handwritten notes on the left margin: "Screwshaft examined 27/6"