

Chief Surveyors

Received from Chief Surveyors

Ship's NAME

SEA MONARCH

Report

Liv.

No. 113150

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

Condition

When due

Subject to indented plating around starboard knee pipe,
it in way of port forward galleys being dealt with at
first convenient opportunity.

CSF
25.9.39



© 2019

Lloyd's Register
Foundation

W311-0157