

Chief Surveyors

Received from Chief Surveyors

NAME YACHT "CAROLITA" Report CGO No. 386

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey 2ND S.S. N^o 1 When due 6-39

noted

was
27.9.40.

It is concluded that there is a steam anchor
on board.

S.P. N.Y.R.
3.11.40



© 2019

Lloyd's Register
Foundation

W314-0209