

while Building, *yes*  
or in Dry Dock

F.E.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *Steel T. S. Yacht "Sona"* Rpt. *Sou.* No. *11316*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/32.

verse No. *86.56.*

Depth "d"

ing: Table No.

Description

*Angles as approved.*

tudinal No. *21664.*

Proportions

Length =  
Depth =

*11.02*

~~Deck~~ Sheerstrake *as approved*

This vessel appears to have been built in accordance with the  
and the approved plans, and it is submitted she is eligible to

assed \* 100 A1 (Steel) in Yacht Register

2 Decks. (U.Tk)

Bk. 7" 4 BH. Cem. Legs across.



*M. © 2019 RKM*  
*10.8.22.*

Lloyd's Register  
Foundation

W319-0153

ny chargeable) £ - *10/6.*  
paid at *Wch.*

Open Hearth process.