

sp "Grete."

Haw 15563.

It is submitted that this report be returned to the Hamburg Surveyors & they should be informed that the area of the wires of the electric light installation as stated therein do not comply with the Rules of this Society & they should be requested to state whether the particulars given are correct.



J.W.D.

3/8/23

© 2020
Lloyd's Register
Foundation

W32-0076