

In damage cases where the Surveyor has not made a special damage report he is required to state whether he

Empire Defender

af

W32-0097

702	71-2-14	54-10-0-0 ✓	Bolannia	Sykes	CH. 24-2-20 Paul
701 ✓	69-2-14	53 52-12-2-0 ✓	Byers Stockless	Byers	Sld 15-6-46
73 ✓	66-1-0	52-13-0-14 ✓	" "	"	Haffner Sld 5-7-98
23	64-2-4	50-17-2-0	" "	"	Sld 14/8-22 Green
29	68-3-7	53-2-2-0	Halls Patent.	"	Cdf. 26-2-28 Jones
98	240 fm 2 $\frac{5}{16}$	96 $\frac{1}{4}$ 134 $\frac{3}{4}$	642-3-18 ✓		Rot. 18-9-30. Welchmeyer.
8	15 fm 2 $\frac{3}{8}$	101 $\frac{1}{2}$ 142 $\frac{1}{10}$	43-1-7 ✓		Sld. 18-9-22 Butler.
	15 " 2 $\frac{5}{16}$	96 $\frac{1}{4}$ 134 $\frac{3}{4}$	42-3-0 ✓		Rob. 16-10-29 Williams
78	15 " " "	" "	42-1-0		Cdf. 26-2-28 Jones

The original equipment has been replaced
by equipment as above up to 1934 date
of vessel being taken out of class
since then no knowledge of
what may have happened to equipment
Rld