

ent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME

SH Le 'AVALONA STAR'

Report

Yak

No. 19413.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Alterations

When due

The 1st S.S. No 1 has been held on hull.

Noted

WAB

2-6-32

Amend:- 3 dks (stk) 4th dk (stk) in No 1, 2, 3, 5 & 6 holds.
 to :- 4 dks (stk) 5th dk (stk) in No 1, 2, 3, 5 & 6 holds.
 Delete:- P 68' B 285' F 78' + Promenade dk 172'
 Insert:- B 172'

© 2020

 Lloyd's Register
 Foundation
 W334-0068