

Jan. 12. 20.

1

Anchona class

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Ste T.S.S. AVELONA* Report *Sl* No. *46631*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey *1st Entry* When due *Revised* Rule

* 100 A. I. (Steel). "With Freeboard"
 3 D^o (Stl), 4th D^o (Stl) in No 1. 2. 3. 5 & 6 holds
 Cell D.B. 421' 1770t, Tanks at sides of tunnels 188t, F.P.T. 97t, A.P.T. 86t.
 F.K, Duct Keel forward of machinery space 152', Q.B.H, Com, Lloyds ARCP.
 P68', B 285', F 78'. Homemade D^o 172'.



© 2020
 11.5.027

Lloyd's Register
 Foundation
 W334-0155

Is fee paid?

Form for Certificate

Instructions

Date