

COPY

Rpt. 12.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

Port SUNDERLAND

When received in London Office

Vessel's Name BARBARA MARIE

Official No. _____ No. in Reg. Book _____

Port of Registry (For Foreign Vessels) _____

Iron or Steel _____ State whether Classed by Lloyd's Register _____

Name of Owners _____ Date of Verification 2.4.28

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line 3 ft. 3 ins.From centre of disc to top of statutory deck line }
at awning or part-awning deck . . . } ft. ins.Fresh Water line above centre of disc . . . 6 $\frac{3}{4}$ ins.Indian Summer line above centre of disc . . . 5 $\frac{1}{2}$ ins.Winter line below centre of disc . . . 5 $\frac{1}{2}$ ins.Winter North Atlantic line below centre of disc --- ins.Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of ~~wood~~ steel deck with the vessel's side } at ~~main, spar or~~ upper dk. 1 $\frac{3}{4}$ ins.
at awning or pt.-awning dk. --- ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or steel deck.

Surveyor.

(To be filled up in London Office.)

Statement No. _____ Date of Committee's Minute 21.3.28

Particulars for record in Register Book.	{	Moulded Depth . . .	<u>27</u>	ft.	<u>6</u>	ins.
		Freeboard . . .	<u>3</u>	ft.	<u>3</u>	ins.
		Corresponding Draught	<u>24</u>	ft.	<u>7</u>	ins.

Freeboards compared and found correct by _____ Date _____

Is fee paid? _____ Form for Certificate _____


Instructions _____ Date _____

Certificate written _____ Noted for posting _____

2m, 11, 21.—T.

Tonnage Opening Fitted.

Condition of Class



© 2020

Lloyd's Register
Foundation

W336-0103