

142341 War Pointer 1918 London

Bassa

1m.12.15.

F.E.

Received by Chief Ship Surveyor 9.4.18 Received from Chief Ship Surveyor

VESSEL'S NAME Shells War Pointer Rpt. Five No. 70831

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 83. Depth "d" 18.4  
Framing: Table No. 3 page 15 Description Bulb Angle as approved  
Longitudinal No. 33200  
Proportions Length = 10.2  
Depth =

Bridge Deck Sheerstrake as approved.

The downcomer pump & Reddy Anchor have been dispensed with as approved for Standard Vessels.

The oil tanks are stated to have been fitted for carrying oil fuel.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A-1 (Steel) as recommended.

2 Dks (Steel)

Cell D.B. 345' 1113L. F.P.T. 118L. A.P.T. 174L

FLK. 7 BH. pl. Cam. P49' B112' F39' Lloyd's Reg. P.

Carrying oil fuel F.P. above 156°F in D.B.

M  
10.4.18



© 2020

Lloyd's Register Foundation  
W338-0026

No. of Owners

Owner if there are more owners than one.

William Joseph