

W347-0120

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *St. S. M/V "MOORDRECHT"* Rpt. *Rot* No. *19937*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

*P. Lang*  
Transverse No. *15295*

Depth "d"

Framing: Table No. *✓*Description *Longitudinal framing at bottom and at deck*Longitudinal No. *40918*

Proportions  $\frac{\text{Length}}{\text{Depth}} =$  *12.54*

Deck Sheerstrake *as approved*

Revised Rules

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100A.1. (Steel). Carrying Petroleum in Bulk  
 1<sup>st</sup> D<sup>ck</sup> (Stl), 2<sup>nd</sup> D<sup>ck</sup> (Stl) in way of machinery space, web frames  
 Longitudinal framing at bottom and at deck  
 Cell D.B. & E. 32' 595, D.T.f 25' 2435, F.P.T. 2205, A.P.T. 1365  
 F.K., 12 B.H., Clays ACP  
 P 110 F 44  
 Machy app.

The surveyor should be requested to forward a copy of the midship section of the vessel as built. *18/12/30*

© 2020

17.12.30

Lloyd's Register Foundation